

# 2018 PETERBILT 579 Sleeper



## Equipment Information

**Price:** \$34,500  
**Location:** Fontana, CA  
**Unit Number:** 2214592  
**Unit Address:**  
**City:** Fontana  
**State:** CA - California

### Comments:

POWER STEERING PUMP IS LEAKING FLUID INTERNALLY TO THE ENGINE. found engine oil to be low #power steering overfull #need to change the oil and filters on engine and re-test #also recommend replacing the power steering pump and fluid change with filter. INSPECTED COOLANT AND FOUND TO BE CONTAMINATED, TESTED FOR COMBUSTION GASSES IN THE COOLING SYSTEM AND FOUND TO BE POSITIVE. ISOLATED CYLINDER HEAD AND FOUND UNIT TO BE BUILDING PRESSURE FROM HEAD. UNIT APPEARS TO HAVE FAILED HEAD GASKET. WE WILL NEED TO REMOVE THE HEAD, INSPECT FOR DAMAGE TO PISTONS AND LINERS, INSPECT BLOCK, IF ALL CHECKS OUT UNIT IS GOING TO NEED HEAD GASKET REPLACED.



<b>Make</b>	PETERBILT
<b>Model</b>	579
<b>Year</b>	2018
<b>Mileage</b>	766,765



<b>Fuel Type</b>	Diesel
<b>Drivable</b>	No
<b>Unit Starts and Runs</b>	Yes
<b>Check Engine Light</b>	Off
<b>ABS Light</b>	Off
<b>Engine Derated</b>	No
<b>Needs Towed</b>	Yes
<b>Cab</b>	Sleeper
<b>Engine</b>	MX13 PACCAR
<b>Transmission</b>	Manual FULLER
<b>State</b>	CA - California
<b>City</b>	Fontana
<b>Wheel Or Hook</b>	Fifth Wheel
<b>Steer Tire Size</b>	295/75/R22.5
<b>Drive Tire Size</b>	295/75/R22.5
<b>Rear Suspension</b>	Air
<b>Rear Suspension Rating</b>	40,000
<b>Rear Axles</b>	Locking

<b>Wet Kit</b>	N_A
<b>APU</b>	Yes
<b>APU</b>	Thermoking
<b>Last DOT Inspection</b>	2024-05-03
<b>Out of Service Date</b>	2024-04-03

<a href="#">email.pdf</a>
<a href="#">KENAN 43713460.pdf</a>