



Ohio Peterbilt - Youngstown PB

3682 Leharps Dr Youngstown, Ohio 44515

Phone: (330) 793-4421



Case Number: 21151544

Repair Order Number: 34804

Purchase Order Number: N/A

Service Advisor: Merchant, David - Case Date 2026-09-03 20:16:22 -0400

ETR: 9/14/2026 at 12:00 pm EDT

Customer: Kenan Advantage Kage Newell, Wv

Unit Number: 1113339

Address: 180 QUAKER STATE ROAD
NEWELL, WV 26050

Phone: (877) 213-1622

Fax: N/A

Customer Number: 20030

Asset: 2017 Peterbilt 579

Serial Number: HD432140

VIN: 1XPBDP9X3HD432140

Engine: MX-13

Engine Hours: 24035

Odometer: 667923 Miles

Warranty Start: 10/07/2016 12:00:00

In Service: 9 Years 11 Months

1 Peterbilt Courtesy Inspection [WARRANTY] [999-999-000]

Complaint: PERFORM COURTESY INSPECTION

Correction: PERFORMED COURTESY INSPECTION

PTO DRIVE SHAFT; BOTH U-JOINT CROSSES BLOWN OUT

		Quantity	Price	Core Price	Totals
Labor:			\$0.00	n/a	\$0.00
Additional Charges:	ShopSupp, Shop Supplies Percentage	n/a	\$15.81	n/a	\$0.00
Operation Total:					\$0.00

2 Diagnostics - Automatic Transmission [027-000-000]

Includes: [Default Variation]

Complaint: TRANSMISSION ISSUES

Correction: DROVE UNIT IN. REMOVED CLUTCH INSPECTION COVER, AND THE HOA CLUTCH ACTUATOR (SERVO), FOUND A LOT OF DEBRIS PACKED IN THE ACTUATOR HOLE, PIECES OF CLUTCH SPRING AS WELL, QUOTING A CLUTCH, WITH A NEW SERVO, THE "BOOT" ON THE SERVO IS TORN, PROBABLY FROM ALL THE DEBRIS, PUT NEW U-JOINT CROSSES ON THE QUOTE AS WELL, FOUND BOTH CROSSES ON PTO U-JOINTS BLOWN OUT ON PRE-INSPECTION. WAITING ON APPROVAL.

			Quantity	Price	Core Price	Totals
Labor:				\$152.00	n/a	\$2,128.00
Parts:	308925-20	*Promo A* CLUT EP 15.5,1860TORQ,VCT DAMPR, 7-SPRNG	1.0		\$0.00	
	E17-1001	SERVO-CLUTCH, HYDRAULIC	1.0		\$0.00	
	5-170X	KIT-U JOINT 1000	2.0		\$0.00	
	E17-6020	HOSE ASSY-HYDRAULIC	1.0		\$0.00	
	G38-1045-0004	FITTING-PLUG J2494 COMPOSITE	1.0		\$0.00	
	Parts Total					\$1,628.34
Additional Charges:	ShopSupp, Shop Supplies Percentage		n/a	\$170.24	n/a	\$170.24
Operation Total:						\$3,926.58



Ohio Peterbilt - Youngstown PB

Customer: Kenan Advantage Kage Newell, Wv	Unit Number: 1113339
Case Number: 21151544	Asset: 2017 Peterbilt 579 VIN: 1XPBDP9X3HD432140

	Parts	\$1,628.34
	Labor	\$2,128.00
	ShopSupp	\$170.24
	Total	\$3,926.58

Notes:

[9/3/2026 at 08:23 pm EDT] - Unit 1113339 was checked in at Ohio Peterbilt - Youngstown PB. Arrival time: 9/3/2026 at 08:00 pm EDT.
NOTE: CHECKED INCase status set to Checked-in.

[9/9/2026 at 08:24 am EDT] - Good morning,

Can I please get an update on this unit?

Thank you.

[9/9/2026 at 08:00 pm EDT] - PERFORMED COURTESY INSPECTION
PTO DRIVE SHAFT; BOTH U-JOINT CROSSES BLOWN OUT

[9/9/2026 at 08:01 pm EDT] - DROVE UNIT IN. REMOVED CLUTCH INSPECTION COVER, AND THE HOA CLUTCH ACTUATOR (SERVO), FOUND A LOT OF DEBRIS PACKED IN THE ACTUATOR HOLE, PIECES OF CLUTCH SPRING AS WELL, QUOTING A CLUTCH, WITH A NEW SERVO, THE "BOOT" ON THE SERVO IS TORN, PROBABLY FROM ALL THE DEBRIS, PUT NEW U-JOINT CROSSES ON THE QUOTE AS WELL, FOUND BOTH CROSSES ON PTO U-JOINTS BLOWN OUT ON PRE-INSPECTION. WAITING ON APPROVAL.

[9/9/2026 at 08:06 pm EDT] - Approval Requested for the estimate version 1. Total \$3,926.58. NOTE: UPDATED NOTES ON DECISIV PERTAINING TO THE QUOTERepair status set to Pending Approval.



Ohio Peterbilt - Youngstown PB

Customer: Kenan Advantage Kage Newell, Wv	Unit Number: 1113339
Case Number: 21151544	Asset: 2017 Peterbilt 579 VIN: 1XPBDP9X3HD432140

This estimate valid for 30 days from date above. I, the undersigned, authorize you to perform the repairs and furnish the necessary materials. I understand that any estimates are based on your preliminary inspection and do not cover any additional parts/labor that may be required after the work has been started. Occasionally, worn or damaged parts are discovered that may not be evident on the first inspection. Because of this, estimated prices are not guaranteed. I understand any costs verbally quoted are an estimate only and not binding. Estimate is subject to change. Ohio Peterbilt employees may operate vehicle for inspecting, testing and delivery at my risk. Ohio Peterbilt is not responsible for loss or damage to vehicle, unit or articles left in vehicle or unit in the case of fire, theft or any other circumstance beyond our control. Written authorizations will be required for any additional items greater than 10% of original estimate. I understand that the work performed by Ohio Peterbilt may not be covered by warranty and that the manufacturer or warranty company will be the one to make the final determination as to what work will be covered by warranty. Your invoice will not be higher than the estimate by more than 10% unless you approve a larger amount before repairs are finished. In the event you authorize commencement of a repair or service but do not authorize completion, a charge may be imposed for diagnostics performed, disassembly, re-assembly, or partially completed work. Parts replaced under warranty or to be rebuilt or sold by us will not be returned. All other parts will be made available to you when requested, in writing, prior to services starting. An expressed mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto. *Vehicle storage of \$50.00 per 24 hour period will accrue beginning on the 5th day after repair completion. Vehicle storage of \$50.00 per 24-hour period will accrue for vehicle left for any other reason. All labor carries a six (6) month or one thousand five hundred (1,500) hours of operation, whichever comes first.

AUTHORIZED BY: _____ DATE: ____/____/____

The dealership utilizes the hours published in the factory labor time guide, and/or other independent labor/price time guides. Which reflects an average time requirement for the performance of specific vehicle repairs, and which may, therefore, be either more or less than the actual clock time in any given instance.