

# 2016 PETERBILT 579 Sleeper



## Equipment Information

**Price:** \$10,000

**Location:** Dayton, OH

**Unit Number:** 2211588

**Unit Address:**

**City:** Dayton

**State:** OH - Ohio

### Comments:





ENGINE BAD, ENGINE MOUNTED IN UNIT, NOT HOOKED UP, TRANS ON CATWALK, DRIVELINE ON CATWALK, ACCIDENT REPAIRS DECLINED, BAD SCR, ENGINE REPAIR DECLINED, CANNOT GET D/S WINDOW UP, MANY PARTS IN CAB/SLEEPER OF UNIT

<b>Make</b>	PETERBILT
<b>Model</b>	579
<b>Year</b>	2016
<b>Mileage</b>	640,610
<b>Fuel Type</b>	Diesel
<b>Drivable</b>	No
<b>Unit Starts and Runs</b>	No
<b>Check Engine Light</b>	On



<b>ABS Light</b>	Off
<b>Engine Derated</b>	Yes
<b>Needs Towed</b>	Yes
<b>Cab</b>	Sleeper
<b>Engine</b>	MX13 PACCAR
<b>Transmission</b>	Automatic EATON
<b>State</b>	OH - Ohio
<b>City</b>	Dayton
<b>Wheel Or Hook</b>	Fifth Wheel
<b>Steer Tire Size</b>	LP22.5
<b>Drive Tire Size</b>	LP22.5
<b>Rear Suspension</b>	Air
<b>Rear Suspension Rating</b>	19000
<b>Rear Axles</b>	Locking
<b>Wet Kit</b>	Hydrapak
<b>APU</b>	No
<b>Last DOT Inspection</b>	2022-11-07
<b>Out of Service Date</b>	2023-03-02





[2211588 ACCIDENT 1 DECLINED.pdf](#)

[2211588 ACCIDENT 2 DECLINED.pdf](#)

[2211588 ENGINE REPAIR, DECLINED.pdf](#)

