

# 2015 Volvo VNL-430 Sleeper



## Equipment Information

**Price:** \$20,000

**Location:** Dayton, OH

**Unit Number:** 2210138

**Unit Address:**


**City:** Dayton







**State:** OH - Ohio

### Comments:





CEL ON, NEEDS INTAKE HEATER RELAY & OUTLET NOX, FRONT DIFF LEAK, OIL LEAK AT OIL FILL TUBE, NEEDS HEAT SHIELD & PIPE NEAR DPF, BLEW STEER TIRE NEEDS BODY WORK, STEP, STEP MOUNT, HOOD REPAIR, ETC. AUDIBLE AIR LEAK NEAR D/S OF FIREWALL, WINDSHIELD CHIPPED

|                      |         |
|----------------------|---------|
| Make                 | Volvo   |
| Model                | VNL-430 |
| Year                 | 2015    |
| Mileage              | 711,877 |
| Fuel Type            | Diesel  |
| Drivable             | Yes     |
| Unit Starts and Runs | Yes     |
| Check Engine Light   | On      |





|                        |              |
|------------------------|--------------|
| ABS Light              | Off          |
| Engine Derated         | No           |
| Needs Towed            | Yes          |
| Cab                    | Sleeper      |
| Engine                 | D13 VOLVO    |
| Transmission           | Manual EATON |
| State                  | OH - Ohio    |
| City                   | Dayton       |
| Wheel Or Hook          | Fifth Wheel  |
| Steer Tire Size        | LP22.5       |
| Drive Tire Size        | LP22.5       |
| Rear Suspension        | Air          |
| Rear Suspension Rating | 19000        |
| Rear Axles             | Locking      |
| Wet Kit                | Hydrapak     |
| APU                    | No           |
| Last DOT Inspection    | 2022-04-25   |
| Out of Service Date    | 2022-11-15   |



[2210138 BODY WORK ESTIMATE.pdf](#)

[2210138 DECLINED REPAIR QUOTE.pdf](#)