

1989 BRENNER CHEMICAL

Equipment Information

Price: \$6,500
Location: Baytown, TX
Unit Number: 601R008
Unit Address:
City: Baytown
State: TX - Texas

Comments:

FAILED HYDRO TESTING FOUND CRACK AT BOTTOM OF TANK. SPILLBOX DAMAGED AS WELL WILL NEED REPAIRED TOTAL COST OF REPAIR IS \$7693.16

VIN	10BFV7212KF0A1303
Make	BRENNER
Category	CHEMICAL
Type of Unit	MC307SS
Year	1989
Total Capacity	7000
Compartments	1
Category	CHEMICAL
In Transit Heat	No





Type of Suspension	Spring
Insulated	Yes
Lined	No
Audible Air Leaks	No
Unit Drivable	No
Needs Towed	No
Last DOT Inspection	2024-02-29
Out of Service Date	2024-02-29

KAG 1R008 REPAIR ESTIMATE .pdf
since new.pdf
12 month.pdf
601R008 Analysis.xlsx