

# 2018 Peterbilt 579 Sleeper



## Equipment Information


**Price:** \$38,500  
**Location:** Toledo, OH  
**Unit Number:** 60P61861  
**Unit Address:**  
**City:** Toledo  
**State:** OH - Ohio

### Comments:

Cylinder head cracked and was pushing coolant which also caused camshaft failure. Needs major engine work

<b>Make</b>	Peterbilt
<b>Model</b>	579
<b>Year</b>	2018
<b>Mileage</b>	491,245
<b>Fuel Type</b>	Diesel
<b>Drivable</b>	No
<b>Unit Starts and Runs</b>	No
<b>Check Engine Light</b>	On
<b>ABS Light</b>	Off
<b>Engine Derated</b>	Yes





<b>Needs Towed</b>	Yes
<b>Cab</b>	Sleeper
<b>Engine</b>	X15 Cummins
<b>Transmission</b>	Automatic Eaton
<b>State</b>	OH - Ohio
<b>City</b>	Toledo
<b>Wheel Or Hook</b>	Fifth Wheel
<b>Steer Tire Size</b>	11R 22.5
<b>Drive Tire Size</b>	455/55 R22.5
<b>Rear Suspension</b>	Air
<b>Rear Suspension Rating</b>	36,000
<b>Rear Axles</b>	Locking
<b>Wet Kit</b>	Hydraulic
<b>APU</b>	No
<b>Last DOT Inspection</b>	2024-01-09
<b>Out of Service Date</b>	2024-05-17

[Untitled].pdf

