

## A white Volvo 126L semi-truck is parked on a dark asphalt lot. The truck is a conventional cab model with a large chrome grille featuring the Volvo logo. The number '126' is visible on the side of the hood. It has a tall exhaust stack and dual rear wheels. In the background, there is a blue metal building with an open bay door and some trees under a cloudy sky.



<b>Make</b>	Volvo
<b>Model</b>	VLN
<b>Year</b>	2016
<b>Mileage</b>	973,707
<b>Fuel Type</b>	Diesel
<b>Drivable</b>	Yes
<b>Unit Starts and Runs</b>	Yes
<b>Check Engine Light</b>	On
<b>ABS Light</b>	Off
<b>Engine Derated</b>	No
<b>Needs Towed</b>	No



<b>Cab</b>	Sleeper
<b>Engine</b>	D13J425 Volvo
<b>Transmission</b>	Automatic Volvo
<b>State</b>	WI - Wisconsin
<b>City</b>	Green Bay
<b>Wheel Or Hook</b>	Fifth Wheel
<b>Steer Tire Size</b>	275/80R22.5
<b>Drive Tire Size</b>	295/75R22.5
<b>Rear Suspension</b>	Air
<b>Rear Suspension Rating</b>	38,000
<b>Rear Axles</b>	Locking
<b>Wet Kit</b>	N_A
<b>APU</b>	No
<b>Last DOT Inspection</b>	2023-10-11
<b>Out of Service Date</b>	2023-10-11